


S U R V E Y
in
South $\frac{1}{2}$, Sec. 1, Montgomery Twp.
Wood Co. O.

598
MONTGOMERY



Control points found at points shown thus \triangle
Iron pipe set at points shown thus \odot

Surveyed by H. Morgan
Apr. 1976 Reg. Sur. 390

598
MONTGOMERY