

533  
MONTGOMERY

SURVEY  
in  
S.E. 1/4, Sec. 10, Montgomery Twp.  
Wood Co., O..  
for  
The Henry Bros.


Control points shown thus ——— \*  
Iron pipe set at points shown thus ◆  
P.K. nails set at points shown thus •

N.. Line S.E. 1/4 S.E. 1/4

N.E. cor.  
Sec. 10

E. Line  
S.E. 1/4  
Pemberville  
Rd. 50' RW

4.19 ac.



Surveyed by H. Morgan  
Aug. 1966 Reg. Sur. 890

Center Line S.R. 281  
60' RW

S.E. Cor.

