

365
LIBERTY

S U R V E Y


in
S.E. 4, Sec. 26, T 4 N-R 10 E, Liberty Twp.
Bays Ohio

Control points found at points shown thus ▲
Iron pipe set at points shown thus ●

Surveyed by H. Morgan
April 1973 Reg. Sur. 890

N.E. Cor. S.E. 4

E. Line Sec. 26
Rudolph Rd.



365
LIBERTY